

Before and After





Along this run of pipe, the bottom portion was displaced and rolled up blocking much of the pipe.



Bottom portion of pipe is completely missing.