SURVEYOR'S REAL PROPER. Y REPORT

THIS DOES NOT CONSTITUTE A BOUNDARY SURVEY

This inspection and its control points are subject to the inaccuracies that a subsequent boundary survey may disclose. It is not to be used for the establishment of any fences, structures or other improvements. To establish the boundary lines, I recommend a Land Surveyor Registered in your state prepare a Boundary Survey. Said inspection and the accompanying sketch are true and correct to the best of my information, knowledge and belief any, were prepared for mortgoge little insurance only. The Flood Hazard Zone for this property has not been determined unless otherwise anted. No property set or angular values shown bereon, if any, are from plat or deed information, and have not been verified unless moted. No warranty is extended therein to the present or future owner or occupant. This inspection was either conducted by me or under my direct supervision. J.B.B.

JOB NUMBER. 103625 SCALE: 1"=20 John M. Snider J.D. Reece 202 West Third st. Tricia DESCRIPTION: Beginning at at point 23 feet North of the Southwest corner of the Lee's Summit, Missouri Southeast 1/4 of the Southeast 1/4 of Section 6, Township 47, Range 31, thence East 88 feet, thence North 111.3 feet, thence North 19 degrees 44 Minutes West to a point which is 183 feet North of the South line of Section 6, thence West to the West line of said 1/41/4 section, thence South 160 feet to the point of beginning Lee's Summit, Jackson County, Missouri. DETACHED GARAGE 30 76 4 LS-2445 J. BERNARD 0 - Control Point & ASSOCIATES Liability is hereby limited to the above ordered by and or their assigns and Title Company of the initial closing) Is PROHIBITED AND NO LABILITY WILL HE ASSUMED. Properly address and encruachments, if any, are shown on the above diagram. Note: Positional tolerance of major improvements location shown is \$0.50 unless otherwise unicd. EYORS, INC. Commitment No. 95110392 6505 EA T PRONTAGE ROAD, SU MERRIAM KANSAS 66202 9

432-8696