

## CIPP Lining and LCRs Project

## Change Order Details

CIPP Lining and LCRs Project

**Description** BASE BID: Work shall consist of the rehabilitation of approximately 3,900 linear feet of 15-inch diameter pipe, 430 linear feet of 12-inch

diameter pipe, and 500 linear feet of 8-inch diameter pipe through Cured-in-Place Pipe (CIPP) Lining. ADD ALTERNATE NO. 1: The Work

shall consist of lateral connection repairs of an area that includes approximately 25,580 linear feet and repairs 82 connections. ADD

ALTERNATE NO. 2: The Work shall consist of lateral connection repairs on an area that includes approximately 16,400 linear feet and repairs

185 connections.

**Prime Contractor** Kissick Construction

Change Order

**Status** Pending

**Date Created** 01/27/2025

**Type** City Council Approval

Summary Change Order 1

**Change Order Description** Adding additional items for Lateral Connection Repair (LCR) work to use all ARPA Legislative Priority Grant money available to the City.

**Awarded Project Amount** \$1,233,922.00

**Authorized Project Amount** \$1,233,922.00

**Change Order Amount** \$683,610.00

**Revised Project Amount** \$1,917,532.00

Change Order Details:
CIPP Lining and LCRs Project

01/27/2025

## **New Items**

Line Number	Item ID	Unit	Quantity	<b>Unit Price</b>	Extension
Section: D - Area 3					
30-C	New Item(s)	LS	1.000	\$5,000.000	\$5,000.00
New Item: Mobilization					
31-C	New Item(s)	LS	1.000	\$1,000.000	\$1,000.00
New Item: Erosion Conf	trol and SWPPP Documentation				
32-C	New Item(s)	LS	1.000	\$3,000.000	\$3,000.00
New Item: Bypass Pump	ping				
33-C	New Item(s)	LF	24,080.000	\$2.900	\$69,832.00
New Item: Pre-Lining C	CTV Video Inspection - 8" Sew	er Main, including Heavy	Cleaning		
34-C	New Item(s)	LF	1,010.000	\$4.500	\$4,545.00
New Item: Pre- Lining (	CCTV Video Inspection - 10" Se	wer Main, including Heav	y Cleaning		
35-C	New Item(s)	LF	1,055.000	\$4.500	\$4,747.50
New Item: Pre- Lining O	CCTV Video Inspection - 12" Se	wer Main, including Heav	y Cleaning		
36-C	New Item(s)	EA	193.000	\$1,700.000	\$328,100.00
New Item: Lateral Conn	ection Repairs				
Section: E - Area 4					
37-C	New Item(s)	LS	1.000	\$5,000.000	\$5,000.00
New Item: Mobilization					
38-C	New Item(s)	LS	1.000	\$1,000.000	\$1,000.00
New Item: Erosion Cont	trol and SWPPP Documentation				

Change Order Details:

01/27/2025

CIPP Lining and LCRs Project

Page 2 of 3

Line Number	Item ID	Unit	Quantity	Unit Price	Extension
39-C	New Item(s)	LS	1.000	\$3,000.000	\$3,000.00
New Item: Bypass Pump	ping				
40-C	New Item(s)	LF	15,995.000	\$2.900	\$46,385.50
New Item: Pre-Lining C	CCTV Video Inspection - 8" Sew	er Main, including Heavy	Cleaning		
41-C	New Item(s)	LF	625.000	\$4.500	\$2,812.50
New Item: Pre- Lining O	CCTV Video Inspection - 10" Se	wer Main, including Heav	y Cleaning		
42-C	New Item(s)	LF	775.000	\$4.500	\$3,487.50
New Item: Pre- Lining (	CCTV Video Inspection - 12" Se	wer Main, including Heav	y Cleaning		
43-C	New Item(s)	EA	121.000	\$1,700.000	\$205,700.00
New Item: Lateral Conn	nection Repairs				
14 items					Total: \$683,610.00