

**Lee's Summit Leachate Interceptor Trench
Construction Survey Data
Collected by Wiedenmann, Inc.**

Location	Survey Date	Survey Reading	Depth to Rock	Location	Survey Date	Survey Reading	Depth to Grout	Grout Thickness
start	9.17.2018	8.80	6.80	start	9.18.2018	5.86	4.60	2.20
25'	9.17.2018	8.45	6.45	25'	9.18.2018	5.46	4.20	2.25
41'	9.17.2018	8.50	6.50	41'	9.18.2018	5.95	4.69	1.81
50'	9.17.2018	11.92	9.92	50'	9.17.2018	9.26	7.26	2.66
60'	9.17.2018	11.76	9.76	60'	9.18.2018	8.11	6.85	2.91
65'	9.17.2018	13.05	11.05	65'	9.18.2018	8.58	7.32	3.73
70'	9.17.2018	19.44	17.44	70'	9.20.2018	11.26	7.06	10.38
75'	9.17.2018	22.44	20.44	75'	9.20.2018	10.93	6.73	13.71
100'	9.18.2018	21.23	19.97	100'	9.20.2018	8.75	4.55	15.42
118'	9.18.2018	18.45	17.19	118'	9.20.2018	9.29	5.09	12.10
125'	9.18.2018	10.98	9.72	125'	9.20.2018	8.62	4.42	5.30
150'	9.18.2018	10.49	9.23	150'	9.18.2018	8.35	7.09	2.14
175'	9.18.2018	10.38	9.12	175'	9.18.2018	9.09	7.83	1.29
200'	9.18.2018	10.56	9.30	200'	9.18.2018	9.00	7.74	1.56

Benchmark Data

9.17.2018	2.00
9.18.2018	1.26
9.20.2018	4.20